

Report Of Failed Appliances
For all Sites and Locations

RSR

RSR Systems
Waterside House
Falmouth Road
Penryn
Cornwall
TR10 8BD

Appliance Description	Appliance Id	Test Date	Vis	Pol	Earth Cont Ohms	Insulation MOhms	Load kVA	Leakage mA	Touch Leak mA	Sub Leak mA	Flash mA
BUILDING 1 - ROOM 1											
3KW HEATER	AP0023	19/05/04	P	S	>19.99 F	>200 S	1.37 S	0.19 S	S	S	S
EXT LEAD	AP0029	19/05/04	P	F	0.06 P	>200 P	S	S	S	S	S
EXT LEAD	AP0030	19/05/04	P	F	0.06 P	>200 P	S	S	S	S	S
EXT LEAD	AP0028	19/05/04	P	F	0.06 P	>200 P	S	S	S	S	S
VIS FAIL	AP0027	19/05/04	F	S	0.07 S	>200 S	1.37 S	0.19 S	S	S	S
Total Appliances:											5
BUILDING 1 - ROOM 2											
EXT LEAD 5	AP0034	19/05/04	P	F	0.31 P	>200 P	<0.05 S	<0.10 S	S	S	S
EXT LEAD DOUBLE	AP0031	19/05/04	P	F	0.17 P	>200 P	S	S	S	S	S
EXT LEAD LONG	AP0035	19/05/04	P	F	0.44 P	>200 P	1.38 S	0.18 S	S	S	S
EXT LEAD QUAD	AP0033	19/05/04	P	F	0.26 P	>200 P	1.39 S	0.18 S	S	S	S
EXT LEAD TRIPLE	AP0032	19/05/04	P	F	0.21 P	>200 P	1.38 S	0.18 S	S	S	S
Total Appliances:											5
BUILDING 4 - ROOM 1C											
EXT LEAD	AP0044	30/06/02	P	F	0.05 P	>200 P	<0.05 S	<0.10 S	S	S	S
IT EQUIPMENT	AP0040	30/06/02	P	S	0.67 F	>200 P	2.10 S	0.18 S	S	<0.10 P	S
LAMP	AP0036	19/05/04	P	S	0.12 F	>200 P	2.10 S	0.18 S	S	S	S
Total Appliances:											3
BUILDING 4 - ROOM 2											
EXT LEAD	AP0045	30/06/02	P	F	0.05 P	>200 P	<0.05 S	<0.10 S	S	S	S
EXT LEAD	AP0046	30/06/02	P	F	0.05 P	>200 P	<0.05 S	<0.10 S	S	S	S
Total Appliances:											2
Total Appliances For Report:											15